


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-252	Smoke	8/27/2009	ADS/TM	S21QQ_001MH	Dry	Yes	771.23



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-252	Smoke	8/27/2009	ADS/TM	S21QQ_001MH	Dry	Yes	771.23

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S19QQ_007G1	S19QQ_007MH	S19QQ_016MH	166.913	8
S19QQ_016G1	S19QQ_016MH	S21QQ_001MH	213.679	8
S21QQ_001G2	S21QQ_001MH	S21QQ_009MH	390.634	8

Observations & Photos

Obs_ID S1028-252-OB01

Address 3200 Auchentoroly Terrace

Status Public

Source Catch Basin

Location Alley

Nearest MH S21QQ_009MH

Comments Smoke from catch basin in alley behind 3200 Auchentoroly Terr.



Picture \S1028-252-OB01-P01.jpg

Comments Back of house, 3200 Auchentoroly Terr.

Obs_ID S1028-252-OB02

Address 1603 Gwynns Falls Parkway

Status Private

Source Cleanout

Location Yard - back

Nearest MH S21QQ_001MH

Comments Smoke from cleanout in back yard. 1603 Gwynns Falls Pkwy.



Picture \S1028-252-OB02-P01.jpg

Comments Back of house, 1603 Gwynns Falls Pkwy.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-252	Smoke	8/27/2009	ADS/TM	S21QQ_001MH	Dry	Yes	771.23

Obs_ID S1028-252-OB03

Address 3402 Auchentoroly Terrace

Status Private

Source Cleanout

Location Paved concrete

Nearest MH S19QQ_016MH

Comments Smoke from cleanout in paved concrete behind house. 3402 Auchentoroly Terr.



Picture \S1028-252-OB03-P01.jpg

Comments Back of house, 3402 Auchentoroly Terr.

Obs_ID S1028-252-OB05

Address 3410 Auchentoroly Terrace

Status Private

Source Downspout

Location Other

Nearest MH S19QQ_007MH

Comments Smoke from downspout on back side of 3410 Auchentoroly Terr.



Picture \S1028-252-OB05-P01.jpg

Comments Back of house, 3410 Auchentoroly Terr.

Obs_ID S1028-252-OB04

Address 3404 Auchentoroly Terrace

Status Private

Source Cleanout

Location Paved concrete

Nearest MH S19QQ_016MH

Comments Smoke from cleanout in paved concrete behind house. 3404 Auchentoroly Terr.



Picture \S1028-252-OB04-P01.jpg

Comments Back of house, 3404 Auchentoroly Terr.

Obs_ID S1028-252-OB06

Address 3408 Auchentoroly Terrace

Status Private

Source Cleanout

Location Paved concrete

Nearest MH S19QQ_007MH

Comments Smoke from cleanout in paved concrete inside garage. 3408 Auchentoroly Terr.



Picture \S1028-252-OB06-P01.jpg

Comments Back of house, 3408 Auchentoroly Terr.

